

Version 108 (8/22/22) Update

Effective August 31st, 2022, all 1168 Wireless Smoke/CO/Low Temp Detectors are being manufactured with Version 108 (8/22/22) software.

Low Battery Alert Update

After working with the manufacturer of the 1168 Smoke/CO combo units, DMP believes that a number of the low battery alerts that some customers experienced were false due to the way the detector defined a low battery and because of improper contact on the battery terminals. This update was created to more reliably determine if a low battery message is valid from the sensor before reporting it to the panel.

Obtaining the New Software

1168 Wireless Smoke/CO/Low Temp Detectors with Version 108 firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.

Existing devices with prior versions of firmware can be updated to the newest version by following the standard DMP process for repair.