

## TECHNICAL UPDATE | AUGUST 2023

### Version 108 (8/7/23) Update

Version 108 (8/7/23) firmware is released for the 1168 Wireless Smoke/CO Detectors.

### Sounder Synchronization Update

Previously, multiple 1168 Wireless Smoke/CO Detectors would take over a minute to synchronize when they announced. 1168 Wireless Smoke/CO Detectors with Version 108 firmware will be available when current inventory has been depleted.

### Obtaining the New Firmware

1168 Wireless Smoke/CO Detectors with Version 108 firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting [buy.dmp.com](https://buy.dmp.com).

Existing devices with prior versions of firmware can be updated to the newest version by following the standard DMP process for repair.