Version 755 Update

Firmware Version 755 (8/5/26) is now available for XR International Series Control Panels.

Wireless Zone Missing Status

Previously, a wireless zone needed to return to a **Normal** state before a **Sensor Reset** could be performed to clear its **Missing** status. This could make troubleshooting wireless issues difficult when a door or window remained open after the wireless zone was no longer missing.

Now, after communication with the wireless zone is restored, an authorized user can perform a **Sensor Reset** to clear the **Missing** status, regardless of the zone's current state.

Deleted Zone Status

Previously, deleting a zone did not clear all existing status information associated with the zone, which could cause the deleted zone to remain in the **Zone Status** list and prevent its status from being cleared.

Now, deleting a zone clears any existing status information associated with that zone.

Wireless Zone Status Display

Previously, when a wireless zone had **Disarmed Open** in **Zone Information** set to **None**, checking the **Zone Number** in **Zone Information** could display an incorrect zone state. The correct zone state was displayed in other menus, including **Zone Status** in the **User Menu** and the **Diagnostics** menu.

Now, **Zone Number** displays the correct state for wireless zones when **Disarmed Open** is set to **None**.

Obtaining the New Firmware

The newest update is available for download, free of charge, on Dealer Admin Global (dealer.eu.securecomwireless.com).

TU-1619 © 2026 Digital Monitoring Products, Inc.