

## HARDWARE UPDATE

### Hardware Update

Effective June 2020, all CellCom-LTE Universal Communicators are shipping with updated hardware. The following features are available:

#### Updated PCB Platform

CellCom communicators have been updated to use the same PCB platform as DualCom communicators (PC-0207). Refer to the included diagram for PCB component locations.



#### CellComF-LTE Additional Tip and Ring Terminal

CellComF-LTE fire communicators now include a total of two tip and ring terminals. Refer to the included diagram for tip and ring terminal locations.

- A** Mounting Holes
- B** Cellular Antenna
- C** SMA Connector
- D** Cell Modem
- E** Tamper
- F** Programming Connection
- G** Terminal Block
- H** Load and Reset Buttons

Previous CellCom PCB PC-0163

New CellCom PCB PC-0207



### Obtaining the New Hardware

To order the new CellCom-LTE Universal Communicators with updated hardware, contact DMP Customer Service at 1-866-266-2826 or visit [buy.dmp.com](http://buy.dmp.com).