

## FEATURE UPDATE | JANUARY 2026

### Version 204/304 Update

1100R/1100RE Series Wireless Repeaters are now being manufactured with Version 204/304 (12/3/25) firmware.

To use this update, [1100XH/1100XHE Series Wireless Receivers firmware Version 210/310 \(11/13/25\)](#) is required.

### Additional Wireless Repeaters

Previously, only 8 repeaters could be connected to a panel. Now, up to 16 repeaters can be connected to XR Series, XF6 Series, and XT75 Control Panels.

The following panel firmware versions are required to use additional wireless repeaters:

- [XR Series firmware Version 253 \(8/22/25\)](#)
- [XF6 Series firmware Version 254 \(9/19/25\)](#)
- [XT75 firmware Version 254 \(9/19/25\)](#)

### Keypad Polling

This update allows the panel to perform faster keypad polling when communicating through wireless repeaters.

### Wireless Connection

This update allows transmitters to connect to a nearby receiver or repeater more quickly.

### Obtaining the New Firmware

1100R/1100RE Wireless Repeaters with Version 204/304 firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting [buy.dmp.com](http://buy.dmp.com).