

### Version 201 Update

1112 Wireless Water and Temperature Detectors are now being manufactured with Version 201 (7/15/25) firmware.

### Low Battery Improvement

Previously, 1112 devices with serial numbers from 08184182 to 08193887 occasionally reported low battery conditions at 2.5 V. Now, the 1112 correctly reports low battery conditions at 2.1 V.

A limited number of 1112 devices were shipped with an earlier firmware version, despite the product label indicating the latest firmware. In some cases, the earlier firmware may result in premature low-battery notifications.

All units in current inventory have been updated, and current shipments include the correct firmware version.

### Obtaining the New Firmware

1112 Wireless Water and Temperature Detectors with Version 201 (7/15/25) firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or visiting [buy.dmp.com](https://buy.dmp.com).

If a low-battery notification is received from an 1112 device that was purchased prior to January 9, 2026, units can be shipped to our repair department to receive a firmware update. Contact DMP Technical Support at 888-436-7832 for any questions.