

Keypad Version 186.1.0.1405 Update

The 8860 Series 7-inch Touchscreen Keypads have been updated to Version 186.1.0.1405.

V-4061DB Streaming

Previously, some 8860 Series keypads were not able to stream V-4061DB doorbells. This issue has been resolved and all V-4061DB doorbells now display as intended.

Duplicate Display Correction

Previously, some 8860 Series keypads were displaying duplicate doorbell streams in the doorbell list. Now, the correct number of streams display.

Obtaining the New Firmware

Firmware updates are available on Dealer Admin (dealer.securecomwireless.com) and in the **Installer Options** menu on the keypad. Follow the instructions below to update the keypad firmware on Dealer Admin and at the keypad.



Note: This update could take several minutes. If you are updating from Dealer Admin, please refresh the page to verify that the keypad has checked in with its new version number.

Update the Keypad on Dealer Admin

1. Ensure that the keypad is connected to the Wi-Fi network before proceeding.
2. Navigate to Dealer Admin.
3. Select the user and system.
4. Next to the keypad name, select **Update**.

Update the Keypad in Installer Options

1. Ensure that the keypad is connected to the Wi-Fi network before proceeding.
2. Select **Options** from the Carousel menu, then select **Installer Options**.
3. Enter **3577** and enter **CMD**. Select **Check for Updates**. Follow the on-screen prompts.