



TECHNICAL UPDATE | DECEMBER 2025

Version 255 Update

Updated Version 255 (12/30/25) firmware is now available for XR Series Control Panels.

Zone Tamper Messages

Previously, the panel sometimes sent a Zone Tamper message to the receiver instead of a Zone Alarm message if the zone was sent into swinger bypass due to an excessive amount of tamper trips, Now, the panel sends the correct Zone Alarm messages to the receiver.

Obtaining the New Firmware

XR Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).